

X	#	Item	Number	Tool	Torque ft-lb	Torque N*m
	1	50-Amp Fuse	1	-	-	-
	2	Negative Battery Cable	1	13mm	tight	tight
	3	Wheels	5 per wheel	17 or 19mm	85	115
	4	Exhaust	3	14mm x 2	22	30
	5	O2 Sensor	1	plug	-	-
	6	Wideband O2	1	plug	-	-
	7	e-brake cable	2	connect	-	-
	8	ECU	3	plug	-	-
	9	MAF	1	connect	-	-
	10	Intake	1	8mm clamp	tight	tight
	11	Fusebox	2	10mm	tight	tight
	12	Fuse blocks	5	7mm	tight	tight
	13	Coolant Hoses	2	8mm clamp	tight	tight
	14	Over flow bottle hoses	1	8mm clamp	tight	tight
	15	Overflow sensor	1	plug	-	-
	16	Shifter Cables to trans	2	clip	-	-
	17	Shifter Cables to Plate	2	15/16	tight	tight
	18	Rear tie rod cotter key	2	side cutters	-	-
	19	Rear tie-rods	2	18mm	35	47
	20	Reverse Sensor	1	plug	-	-
	21	Fan Plug	1	single plug	-	-
	22	Engine Plug (blue tape)		plug	-	-
	23	Axle Nut	2	30mm	135	183
	24	Lower Ball Joint	2	15mm x 2	60	81
	25	Half Shaft	3	15mm	?	?
	26	Clutch line from metal block	1	pick tool		
	27	Front Eng/Trans Mount	3	18mm	74	100
	28	Rear Eng/Trans Mount	3	17 & 15mm	44	60
	29	Front Subframe	2	15/16	100	135
	30	Rear Subframe	2	21mm	100	135
	31	Drivers Eng Mount	1	15mm	37	50
			2	17mm	37	50
	32	Passenger Engine Mount	3	15mm	37	50
	33	Two lower trans bolts	2	18mm	55	74
	34	Boost guage line	1	plug	-	-
	35	HX lines	2	8mm clamp	-	-
	36	Starter wires	3 wires +	15mm	tight	tight
			1 purple wire	7mm	tight	tight
	37	Starter Bolts	2	15mm	30	41
	38	Engine on Roller	-	-	-	-
	39	Vacuum Line Mani/Booster	1	clip to manifold	-	-
	40	Rest Trans Bolts	5	18mm	55	74
	41	Pressure Plate Bolts	6	E30	21	28
	42	Flywheel Bolts	8		39 + 25 deg	53 + 25 deg

Before Starting	X
Bleed Clutch	
Bleed Brakes	
HX Coolant	
Dexcool (engine)	
Fuel Prime	
50-Amp Fuse	
Negative Cable	
B+ Terminal	